

[Back](#)

Use and Features : Weigh the weight of body Foot-tap Switch Automatic Zero Resetting Automatic Swich off OverLoad and Low Battery Indicator	
1. Capacity	150 Kg/330 lb/24 st
2. Division	100 g/0.2 lb
3. Display	LCD Display 25mm(1.0"), 4 and 1/2 digits
4. Precision	0 to 100Kg, $\pm 0.3\text{Kg}$; 100Kg to 150Kg, $\pm 0.4\text{Kg}$
5. Operation Temperature	$25^{\circ}\text{C} \pm 15^{\circ}\text{C}$
6. Safe Overload	150%F. S
7. power	2 pcs of lithium battery included (CR2032)
8. Center Warp	$50\text{Kg} \pm 0.3\text{Kg}$
9. Size	300mm (L) * 300mm (W)
10. Material	glass
11. Color	white, blue and green

