




Integrated Silicon Solution, Inc.

IS23SC4402/04/08/16/32

Features

- 8051 based MCU manufactured with CMOS technology
- Enhanced 16-bit arithmetic and 3 times faster than conventional 8051
- Single 2.7V to 5V power supply with Vpp generated internally
- Additional instructions optimized for chip card applications
- Three 16-bit timers
- Programmable Watchdog Timer
- Two 16-bit Data Pointers
- Five interrupt sources with three levels of priority
- On-chip oscillator and clock circuitry
- Clock frequency: 1 to 5 MHz at 5V; 1 to 4 MHz at 3V
- 256 bytes internal RAM
- 16K/32K bytes user ROM for application program
- 2K/4K/8K/16K/32K bytes EEPROM for application program and data
- Minimum of 1 Million write/erase cycles; 100 years data retention for EEPROM
- OS program storage and execution in EEPROM area enables customized user applications



Security

- Low/High voltages sensors
- Low/High frequency sensors and filter
- Internal power-on-reset
- 16 bytes security PROM Hardware Protected
- Unique Chip ID for each device
- Memory Address scrambling
- Fast erase of internal RAM triggered by security sensors
- Encryption of data busses and memories with using one key
- True FIPS140-2 compiled Random Number Generator for advanced authentication algorithm
- Proprietary block cipher based on a Digital Chaotic Function

Description

IS23SC44 series 8-bit MCU chips are based on ISSI's advanced CMOS technology. The FIPS140-2 compiled random number generator provides a cost-effective solution for advanced authentication. The crypto engine gives customers more security to protect the COS (Chip Operating System) and applications data. User friendly development tools (emulator) is available to shorten the product time to market for customers.



Integrated Silicon Solution, Inc.



To Order

ISSI REGIONAL SALES OFFICES

Headquarters & West Coast Office

Santa Clara, California
PHONE: 408-588-0800
FAX: 408-588-0805
E-MAIL: sales@issi.com
WWW.issi.com

East Coast Office

Nashua, NH
PHONE: 603-594-4176
FAX: 603-594-4181
E-MAIL: gpolanec@msn.com

Central Office

Dallas, TX
PHONE: 972-488-9691
FAX: 877-716-5582
E-MAIL: lzastrow@flash.net

Europe Office

Devon, England
PHONE: 44-1752-764285
FAX: 44-1752-764289
E-MAIL: glouch@issi.com05

China Offices

Shanghai

PHONE: +86 21 5080 2288
FAX: +86 21 5080 2028
E-MAIL: issish@sh163c.sta.net.cn

Shenzhen

PHONE: 86755-663-3977
FAX: 86755-663-3984
E-MAIL: issi@public.szptt.net.cn

Suzhou

PHONE: 86512-725-0384
FAX: 86512-725-0536
E-MAIL: issisz@public1.sz.js.cn

Beijing

PHONE: 86-10-6824-3301
FAX: 86-10-6816-9097
E-MAIL: issibj@public.bta.net.cn


Hong Kong

PHONE: 852-2319-2211
FAX: 852-2319-2004



Integrated Silicon Solution, Inc.

ISO contact	Pad	Description
C1	Vcc	5V power supply
C2	RST	Reset
C3	CLK	Serial clock
C4	N/C	No connect
C5	GND	Ground
C6	N/C	No connect
C7	I/O	Serial data I/O
C8	N/C	No connect



IS23SC4402/04/08/16/32



Integrated Silicon Solution, Inc.



2231 Lawson Lane • Santa Clara, CA 95054 • Tel: 408.588.0800 • Fax: 408.588.0806 • Email: sales@issi.com

Web: www.issi.com