

[Back](#)

Use and Features : measure pressure in high temp. bear temp. up to 1200 °C in chilling water adjust to high temp. pressure	
1. Capacity Series	0-10-250MPa
2. Total Precision	±0.2Level
3. Repeatability	±0.05%FS
4. Nonlinear Hysteresis	±0.15%FS
5. Stability	±0.25%FS
6. Input and Output Resistance	380 Ω ±10%
7. Capacity Output	1.5mV/V
8. Excitation Voltage	10V (6-12V) DC
9. Non-balance Output on Zero	±10%FS
10. Insulation Resistance	500M Ω
11. Overload	150%
12. Use Temperature	0~80°C
13. Temperature Zero and Sensitivity Drift	±0.03%FS/°C

14. Power	
15. Output	
16. Load Resistance	
17. Zero and Capacity Adjustment Range	

Mount Dimension:

